

Evaluation of Low Energy Lights for Minor Road Lighting

**Twin 14 & 24W T5
32 & 42W CF
50W HPS**



Produced by the *Victorian Sustainable Public Lighting Action Group (VSPLAG) – Technical Reference Group.*

Final Report, Revision 1: 2nd April 2009

Table of Contents

1	INTRODUCTION	3
2	FINDINGS	3
3	EVALUATION PROCESS	4
4	LIGHT OUTPUT	5
4.1	SPACING TABLES	5
4.2	COLOUR	6
4.3	MAINTENANCE FACTOR	6
4.4	EFFECTS OF AMBIENT TEMPERATURE ON LIGHT OUTPUT	7
4.5	EFFECTS OF VOLTAGE VARIATIONS ON LIGHT OUTPUT	7
4.6	LIGHT OUTPUT CONCLUSION	8
5	RELIABILITY	8
5.1	IN-SERVICE FAILURE RATES	8
5.2	THEORETICAL FAILURE RATES	9
6	REPLACEMENT CYCLES	10
7	TECHNICAL SPECIFICATION	11
8	LOAD TESTING	ERROR! BOOKMARK NOT DEFINED.
	APPENDIX 1 – REQUIRED MODIFICATIONS TO LUMINAIRES	13
	APPENDIX 2: LAMP FAILURE RATES	15
	APPENDIX 3 : ELECTRONIC (BALLAST) CONTROL GEAR (ECG) FAILURES RATES	18
	APPENDIX 4 : INFORMATION FROM FIELD TRIALS	20
	APPENDIX 5 : MAINTENANCE FACTOR DETERMINATION	28
	APPENDIX 6: LUMEN DEPRECIATION WITH TEMPERATURE	29
	APPENDIX 7 : T5 TEMPERATURE START-UP TEST	31
	APPENDIX 8 : INPUTS INTO OMR PRICES	32
	APPENDIX 9 : APPROVED MANUFACTURING DRAWINGS	1

1 Introduction

Victorian Councils require a reduction in their energy consumption to meet their Greenhouse Gas emission reduction targets and to benefit the environment.

Approximately 40% of Council's Greenhouse Gas emissions are attributed to Public Lighting energy consumption.

Councils wish to introduce low-energy lighting to reduce their energy consumption & reduce their Greenhouse Gas emissions.

The VSPLAG Technical Reference Group was established in mid 2006 to evaluate energy efficient public light options for minor roads & approve those that were deemed to be technically acceptable and have comparable or better performance than the current standard 80 W mercury vapour (80W MV) light.

The VSPLAG Technical Reference Group is represented by :

- Distribution Businesses ie SP AusNet (Mark Butson), Powercor/CitiPower (Brent Dawson/Rick Hemley) & Alinta (Max Demko/Karl Edwards)
- Councils – Hume & Darebin (Stuart Nesbitt)
- Sustainability Victoria - (Doug McPherson)
- Essential Services Commission - (Carmine Piantedosi)
- Ironbark Sustainability (Technical Consultant) – (Paul Brown/Ray Simms)

2 Findings

The VSPLAG Technical Reference Group found that the T5 (twin 14W & twin 24W) & the compact fluorescent (CF) (32W & 42W) low-energy lights were comparable or better in performance than the current standard, the 80W MV.

The Pierlite T5 twin 14W (part # GS214VIC/P) & twin 24W (part # GS224VIC/P) are deemed technically acceptable having received VSPLAG Technical Reference Group approval of the manufacturing drawing and the luminaire sample – refer to *Appendix 9* for approved manufacturing drawing.

The Sylvania Suburban Eco 32W (part # JS98A03L) & 42W CF (part # JS97A03L) are deemed technically acceptable having received VSPLAG Technical Reference Group approval of the manufacturing drawing and the luminaire sample.

Previous to this report, the CF was deemed technically unacceptable due to lamp failure problems due to vibration (refer to *Section 5*). However the lantern was re-designed to incorporate a lamp support system and a successful 3 month field trial was carried out leading to its approval.

The 50W HPS light was found to be unacceptable due to its yellow light and relatively higher energy consumption.

3 Evaluation Process

The VSPLAG Technical Reference Group evaluated the following low-energy lights :-

- T5 Twin 14W & Twin 24W (Pierlite)
- 32W & 42W Compact Fluorescent (CF) (Sylvania)
- 50W High Pressure Sodium (HPS) (Sylvania)



80W MV (current standard)



T5 twin 14W (Pierlite) low-energy light



32/42W CF (Sylvania) low-energy light



50W HPS low-energy light

The evaluation by the VSPLAG Technical Reference Group consisted of :-

- **Light output** : assessing light outputs, spacing tables, colour, light output depreciation, start-up times, voltage and temperature effects.
- **Reliability** : assessing reliability by reviewing manufacturer data and results from field trials in Victoria & interstate
- **Replacement cycles** : establishing replacement cycles of lamps, PE cells & electronic ballasts – these figures assist the Distribution Businesses to determine their OMR rate to charge Councils for operating, maintaining & replacing lights.
- **Field feedback** : Obtaining & reviewing field-feedback from public lighting Contractors
- **Energy consumption** : Performing load tests on these luminaires & applying for these loads to the placed on NEMMCO's load table

The VSPLAG Technical Reference Group established the criteria for the above & evaluated each of the low-energy lights and determined if the criteria was met - details of the evaluation are contained in the following sections.

4 Light output

The following light output parameters were assessed.

- Spacing Tables
- Colour
- Maintenance Factor (Light output depreciation over time)
- Effects of Temperature Variations
- Effect of Voltage Variations

4.1 Spacing Tables

Criteria : Low-energy lights must have comparable or better spacing table values to the current standard 80W MV light.

Analysis : Spacing tables indicate the theoretical required spacing between light poles to achieve a light output that meets AS/NZS 1158.3.1:2005 Pedestrian area (Category P) for a particular light based on a certain road reserve width & light mounting height. The spacing tables are determined using lighting software. The spacing tables below are based on a lamp test chamber ambient temperature of 25 degrees Celsius.

AS/NZS 1158.3.1:2005 nominates two different light output standards :-

- **Category P4** which applies to new lighting schemes. *Table 1* below shows the minimum required pole spacing to meet the P4 standard. A light mounting height of the 5.5m which applies for standard URD lighting poles has been assumed. * However an increased light mounting height of 6.5m has also been included as this may be adopted as the standard light mounting height in the future as it has the advantages that :-
 - light pole spacings can be increased
 - a T5 twin 14W can be used for a 20m road reserve rather than a T5 twin 24W
- **Category P5** which applies to retrofits of existing lights installed on distribution network poles. The spacing table to meet the P5 standard is shown in the *Table 2* below. A light mounting height of 7.5m has been assumed.

Category P4 Lighting								
Maximum Pole spacing	15m road reserve				20m road reserve			
	5.5m light height		* 6.5m light height		5.5m light height		* 6.5m light height	
80W MV (Urban)	55m		61m		46m		53m	
T5 twin 14W	58m	✓	63m	✓	34m	✗	57m	✓
T5 twin 24W	66m	✓	71m	✓	63m	✓	68m	✓
32W CF	60m	✓	61m	✓	51m	✓	50m	✗
42W CF	60m	✓	65m	✓	53m	✓	60m	✓
50W HPS	56m	✓	61m	✓	48m	✓	54m	✓

Table 1 : Spacing Table for New Lighting Schemes (Category P4 Lighting)

✓ = light spacing same or greater than that of an 80W MV

✗ = light spacing less than that of an 80W MV

Category P5 Lighting				
7.5m Mounting Height	15m road reserve		20m road reserve	
80W MV (Urban)	82m		78m	
T5 twin 14W	83m	✓	82m	✓
T5 twin 24W	92m	✓	91m	✓
32W CF	85m	✓	83m	✓
42W CF	84m	✓	84m	✓
50W HPS	81m	✗	79m	✓

Table 2 : Spacing Table for Retrofitting Lights on Power Poles (Category P5 Lighting)

✓ = light spacing same or greater than that of an 80W MV

✗ = light spacing less than that of an 80W MV

Conclusion : T5, CF & 50W HPS lights have comparable or better light output parameters to the current standard 80W MV light where a ✓ is shown in the above tables.

4.2 Colour

Criteria : Low-energy lights must have acceptable light colour.

Analysis: 50W HPS lights have a yellow light which results in reduced colour rendition and definition compared to a white light thus reducing the perceived levels of safety of pedestrians. Under a yellow light many colours appear less bright or even brown. Results of surveys of the public performed by the Northern Alliance for Greenhouse Action in 2004 & 2005 indicated that the respondents did not support the yellow colour of the 50W HPS lights when compared to the white light of T5 & CF lights.

Conclusion : T5 & CF both have an acceptable white light. However the 50W HPS light is unacceptable due to its yellow light.

4.3 Maintenance Factor

Criteria : Low-energy lights must have a comparable or better maintenance factor to the current standard 80W MV light

Analysis: A light's maintenance factor is a measure of the reduction in light output as the light ages, usually over 4 years (ie typical lamp replacement cycle) – the lower the maintenance factor, the lower the light output. See *Table 3* below.

See *Appendix 5* for more details.

Lamp Type	Maintenance factor (after 4 years)	
80W MV	0.55	
T5	0.76	✓
CF	0.67	✓
50W HPS	0.76	✓

Table 3 : Maintenance Factor

Conclusion : T5, CF & 50W HPS low-energy lights have maintenance factors that exceed that of the 80W MV light.

4.4 Effects of Ambient Temperature on Light Output

Criteria: Low-energy lights must have a comparable or better light output variation to a standard 80W MV light

Analysis : The light output of a linear fluorescent lamp is affected more by ambient temperature variations than the current standard 80W MV lamp whose light output is virtually independent on ambient temperature. For a fluorescent lamp, low temperatures reduce the light output marginally and increase start-up time slightly.

However, test results on a T5 with twin 14W non-amalgam lamps indicate that even at an ambient temperature of 0 degrees Celsius, its light output is equivalent to an 80W MV (whose output is virtually independent of temperature).

The Bureau of Meteorology statistics indicate that an 'average' middle suburb of Melbourne experiences only 0.2% of nighttime hours under 0 degrees Celsius.

The effects of temperature variations on light output for linear fluorescent lamps are reduced with amalgam lamps.

At the time of this report, T5 amalgam lamps were only available in the 24W rating with amalgam 14W lamps possibly being available in the future.

32W & 42W CF lamps are currently available with and without amalgam.

It is recommended that :-

- amalgam 32W & 42W CF lamps be utilised
- amalgam 24W T5 lamps be utilised
- when available, amalgam 14W T5 lamps be utilised

Appendices 6 & 7 provide more information on the performance of the T5 light with temperature.

Conclusion : The T5, CF & 80W HPS lights meet the above criteria for effects of temperature on light output.

4.5 Effects of Voltage variations on Light Output

Criteria : Low-energy lights must have a comparable or better light output variation with voltage changes to that of the 80W MV light.

Analysis: The light output of the T5 & 32/42W CF fluorescent lights are affected less by supply voltage variations than the current standard 80W MV light. This is because the T5 & 32/42W CF lights incorporate electronic ballasts which are less susceptible to voltage changes than iron-core ballasts used in the current standard 80W MV & 50W HPS lights.

Results show that lights with 'electronic control gear' such as the T5 and CF lights are largely unaffected by voltage variation whereas the 80W MV, which has an iron core ballast, varied in light output by around 30% between 220V and 260V.

Conclusion : The T5, CF & 50W HPS lights meet the above criteria for performance with voltage change.

4.6 Light Output Conclusion

From the analysis, the CF and the T5 luminaires are suitable for use. As the 50W HPS does not meet the requirements for colour, it was not reviewed any further.

5 Reliability

5.1 In-service Failure Rates

Criteria : Low-energy luminaires must have comparable or better in-service failure rate to the current standard 80W MV luminaire ie **20-25%** (approx) in-service failure rate¹ over a 4 year period. ¹ Based on average failure rates (for any reason) of Victorian distributors listed in United Energy's 'Submission to the Essential Services Commission' dated 28 June 2004.

Analysis: The results of field trials by Integral Energy, Energy Australia & AGL (Victoria) were analysed to evaluate the failure rates of the T5 & CF with the following results (details of the trials are in *Appendix 4*).

Failure rates of the Energy Australia trial of 1000 T5 lights was found to be 5.8% over a 3 year period. Extrapolating² this failure rate out to 4 years gives a rate of 11.7%.

Integral Energy's trial of approximately 4000 T5 lights over a 4 year period has found the failure rate is acceptable to Integral Energy (no quantitative assessment was performed on the trial).

Results of initial 42W CF field trials identified excessive lamp failures due to vibration. Two modes of failure were identified :-

1. Vibration causing lamp to fall out of lamp holder – this problem has been addressed by the introduction of a lamp locking mechanism
2. Vibration causing glass portion of lamp to fracture where it attaches to the lamp base – a lamp support arrangement has been introduced by Sylvania

Both these problems have been addressed by Sylvania with the introduction of a lamp locking mechanism and a lamp support arrangement. A 3 month field trial of 25 lanterns on Philip Island was carried out with a successful result of all 25 lanterns operating at the end of the trial.

Conclusion : T5 & CF lanterns have an in-service failure rate that meets the above criteria.

² From the T5 lamp life expectancy curve in *Appendix 2*, at 3 years (12483hrs) the lamp failure rate is 2% approx. Converting from 3-hr switching to 11-hr switching using a factor of 1.17, 3 year lamp failure rate is 2%/1.17 = 1.7%. For two lamps, 3 year failure rate is 2 x 1.7% = 3.4%.

For two lamps, the 4 year failure rate is 8.6% (refer to *Appendix 2* for details).

Therefore the additional **lamp** failure going from 3 years to 4 years is 8.6% – 3.4% = **5.2%**

From the T5 ballast life expectancy curve in *Appendix 3*, over 8 years the failure rate is approximately linear at about 0.7% failure per year (based on a 70 degrees C curve).

Therefore the additional **ballast** failure going from 3 years to 4 years is **0.7%**.

Total additional failure rates going from 3 years to 4 years (ignoring PE cell failure rate) is 5.2% (lamps) + 0.7% (ballast) = **5.9%**

So T5 extrapolated 4 year failure rate = **5.8%** (failure rate at 3 years) + **5.9%** (failure rate in 4th year) = **11.7%**

5.2 Theoretical Failure Rates

Criteria : Low-energy lights must have comparable or better theoretical failure rates to the current standard 80W MV light ie **15%** (approx) theoretical failure rate¹ over a 4 year period.

¹ Based on lamp failure rates from manufacturer's data sheets – refer to *Appendix 2*.

The majority of 80W MV luminaire failures are due to lamp failures - ballast failures are negligible due to the robustness of the magnetic (non-electronic) ballast.

However, for the T5 & CF luminaires, the majority of failures is due to the combined failures of lamps and ballasts which are electronic and have limited life-spans.

Failures due to PE cells have been ignored in this study as the PE cell (D2) predominantly used in 80W MV luminaires will also be used in all low-energy luminaires considered in this report.

Analysis : The manufacturers have provided the following data for the expected failure rates of their equipment – refer to *Appendix 2* for lamp failures & *Appendix 3* for ballast failures.

	Theoretical Average Failure Rates per year				
	T5 (twin lamps)			CF	
	4 yr	5 yr	6 yr	4 yr	5 yr
Lamps	2.2%	6.6%	18%	3.5%	>10%

	Theoretical Average Failure Rate per year		
	8 yr	10 yr	12 yr
Electronic Control Gear (CF & T5) ¹	0.7%	1%	1.1%

¹ Both the CF & T5 luminaires utilise the same electronic control gear technology.

T5 Theoretical Failure Rates

From the T5 lamp life expectancy curve in *Appendix 2*, the T5 lamp failure rate at 4 years is 8.6% (for twin lamps).

From the T5 ballast life expectancy curve in *Appendix 3*, over 8 years the failure rate is approximately linear at about 0.7% failure per year (based on a 70 degree C curve²).

² Actual temperature is not known, 70 degrees C is seen to be a 'worse case' temperature

So the theoretical 4 year failure rate for T5 luminaires (ignoring PE cell failure which is assumed small) based on 4 year replacement cycle on lamps and 8 year replacement cycle on the ballast is 8.6% (lamps) + (4 x 0.7)% (ballast) = **11.4%**

CF Theoretical Failure Rates

From the CF lamp life expectancy curve in *Appendix 2*, at 4 years the CF lamp failure rate is 14%.

From the ballast life expectancy curve in *Appendix 3*, over 8 years the failure rate is approximately linear at about 0.7% failure per year (based on a 70 degrees C curve).

So the theoretical 4 year failure rate for CF luminaires based on 4 year replacement cycle on lamps and 8 year replacement cycle on ballast is :-

14% (lamps) + (4 x 0.7)% (ballast) = **16.8%**

Conclusion : With a replacement cycle of 4 years on the lamps and 8 years on the electronic control gear and the PE cell the T5 and CF luminaires theoretical failure rates are comparable or better than the 80W MV.

6 Replacement Cycles

Criteria : Low-energy lights must have comparable or better replacement cycles to the current standard 80W MV light.

Analysis: Replacement cycles refer to scheduled maintenance for components that need replacing during the luminaires life ie

1. Lamps
2. PE cells
3. Electronic Ballasts (complete with MOVs*)

* MOVs are electronic components which help to protect the light from voltage surges.

Refer to *Appendices 2 & 3* for details on lamp & ballast failure rates.

Conclusion : VSPLAG Technical Reference Group has established that the following replacement cycles for T5 & CF lights :-

1. Lamps – bulk change every 4 years (same as 80W MV)
2. PE cells - bulk change every 8 years (same as 80W MV)
3. Electronic Ballasts (complete with MOV's) - bulk change every 8 years (no bulk change of ballast required for 80W MV)

In establishing the replacement cycles, consideration was given to 'fit in' with the current replacement cycles of the 80W MV.

Note : due to the lack of long-term in-service history for T5 & CF lights and no available actual failure rate data, the above replacement cycles are **estimates only** and may change when long-term in-service failure rates become available.

7 Technical Specification

For supply of new low-energy luminaires the following requirements must be met :-

- Distribution Business customers eg Councils must endorse the use of the luminaire
- Low energy consumption (minimum of 55 lumens per watt)
- Low-energy lights must meet AS 1158
- Easy to replace lamp, PE cell & ballast (with MOVs)
- Removable gear tray or Plug-in ballast
- Adequate voltage surge protection over life of light eg MOVs at supply cable terminals (A-N & A-E) & MOV on ballast which will be replaced when ballast is replaced
- Electronic ballast must be an approved type. Approved types are : Osram ECG QUICKTRONIC® DE LUXE and Vossloh-Schwabbe
- T5 lamps must be an approved type. Approved types are :
 - 14 watt - Philips Master TL5 HE 14W/840 (non-amalgam)¹
 - 24 watt – Osram FQ 24W/840 HO CONSTANT FLH1 (amalgam)

¹ At the time of this report, T5 14watt amalgam lamps were unavailable. When they become available they will replace the non-amalgam as the approved T5 14watt lamp.

- PE cells must be an approved type. Approved types are : Selcon Kaga 2 amp D2.
- Lights to be supplied with lamp/s fitted
- Manufacturing drawings, showing the above details where applicable, are to be provided by the supplier for review & approval by the VSPLAG Technical Reference Group
- Sample of luminaire is to be provided by the supplier for review & approval by the VSPLAG Technical Reference Group

For maintenance, other types of lamps (including T5 long-life), PE cells & electronic control gear may be approved by individual Distribution Businesses.

8 Load Testing

The VSPLAG Technical Reference Group organised load testing of the T5 & CF (at a NATA accredited laboratory) – load testing of the 50W HPS was not carried out as VSPLAG assessed it as not being technically acceptable due to the light being a yellow colour.

Load test results were sent to NEMMCO for their approval & insertion into their load table – this is the official site which nominates the load of a particular light.

Appendix 1 – Required Modifications to Luminaires

CF Luminaires

The Sylvania 32W & 42W CF luminaires have been approved ie there are no outstanding modifications to the luminaire.

T5 Luminaires

The Pierlite T5 luminaire has been approved ie there are no outstanding modifications to the luminaire.

See table below for a history of T5 issues/modifications – all these items have been resolved.

Acceptable	Further work recommended	High Priority
------------	--------------------------	---------------

Date first discussed	Item	Detail	Resolution (from manufacture)	Other Comment	Risk after resolution
2006	1. Surge protection	No surge protection has resulted in increased failures – particularly prevalent in Darwin trials	MOV's installed to resolve issue		Very low
	2. Surge protection	Do MOV's need routine replacement?	MOV attached to gear tray		
2/2007	3. Grey terminal Cover	Question about safety issue if it is dislodged	Attachments strengthened		Very low - safety. Maintenance main issue.
2/2007	4. Cable in mounting plate	Single insulated cable pressing on sides of metal slots in mounting plate	Grommets fitted (also see item 7)		Nil
2/2007	5. Mounting stops	Mounting bracket end stop ineffectively halting bracket arm	Stops altered	Different bracket size than in NSW.	Nil
2/2007	6. Screws need retaining	Gear Tray securing screws can fall out	Spring clip mount replaces screws		Nil
8/6/2007	7. Quality checks	a) remove sharp edges on flashing b) MOV not to touch metal body c) No loose wiring	a) Agreed b) Agreed c) Agreed		
8/6/2007	8. Check seals		IP65 test provided		
8/6/2007	9. Durability of clips	Clip broken on one unit	Clip installation process altered	Significantly improved	Med
8/6/2007	10. Wiring of gear tray	Can get caught when replacing	3-Pin plug installed and less congestion developed		
8/6/2007	11. Grommets	Are they durable?	Standard streetlight grommet for Rexel		Nil
8/6/2007	12. Bolts rubbing on ballast		Cover fitted to bolts		Nil

	wiring				
8/6/2007	13. Spigot alignment not exact		Stops work		Nil
8/6/2007	14. Spring release	Gear tray release needs to be stiffened	Release stiffened		
	15. Spring release	Spring clip needs lever away from gear tray	Completed		
8/6/2007	16. Gear tray hinge	Recommend for ease of maintenance gear tray hinge at pole end	N/A	Pierlite indicated not possible	Low or Nil
8/6/2007	17. Attach gear tray to stop it falling		Lanyard attached		
	18. Lanyard needs to be detachable	To ease removal of gear tray	Completed		
8/6/2007	19. Align gear tray	Recommend slots or other for ease of gear tray alignment	Completed		Low or Nil
7/11/2007	20. Relocate cable tie for supply cable	Option 1 (preferred) - directly in front of cable entry channel Option 2 – directly in front of terminal block	Option 1 completed		Low or Nil
7/11/2007	21. Easy install on lamps	(hard to line up lamp pins if tomb-stone not align ie not vertical). Consider levers at two ends.	Levers installed		Low or Nil
7/11/2007	22. Larger lamp label	Orientation when installing ie Lamp Label this End with arrow	Label installed		Low or Nil

Appendix 2: Lamp Failure Rates

T5 Lamp Failure Rates

Based on data from "Philips Master TL5 lamps – February 2006" produced by Philips Lighting B.V.

Life expectancy curve below is from page 23¹.




Figure 4.4.1 Life expectancy with a 3-hr switching cycle

Calculation of lamp life expectancy:

From the figure above, at 4 years (16644 hours), the survival rate of a single lamp based on a 3 hr switching cycle is 95%.

Converting from a 3-hr switching cycle to a 11 hour switching (the actual switching cycle for a PE controlled light) results in 17% (see overleaf for copy of page that refers to this figure) greater life expectancy.

A single T5 lamp 4 year failure rate is 5.0% for 3 hour switching.

A single T5 lamp 4 year failure rate is $5.0/1.17 = 4.3\%$ for 11hour switching.

The twin T5 lamp 4 year failure rate is $4.3\% \times 2 = 8.6\%$ or $8.6/4 = 2.15\%$ per year average

¹ "Philips Master TL5 lamps – February 2006" produced by Philips Lighting B.V.

4.5 Lifetime performance

If the MASTER TL5 lamps are operated on electronic gear, designed according to the specifications mentioned in this documentation, at a 3-hour switching cycle (165 minutes on, 15 minutes off), the lamps will have a rated average lifetime of 24,000 burning hours.




Figure 4.4.1 Life expectancy with a 3-hr switching cycle




Figure 4.4.2 Lumen maintenance /800 colours




Figure 4.4.3 Lumen maintenance /900 colours

Notes on life expectancy curves:

Lamp lifetime is specified as the total number of actual operating hours under specific operating conditions. Philips MASTER TL5 lamps are designed for operating with proper preheated electrodes before lamp ignition is established and in accordance with IEC 60901. This is to ensure also reliable long life when the switching frequency is higher than the standard IEC cycle (165 minutes on, 15 minutes off).

The published curves give typical average values based on measurements made by Philips Quality Department Lighting based on large production batches of lamps and tested under laboratory conditions in accordance with IEC 60901.

In practice, the performance of individual lamps or groups of lamps may deviate from the average.

Lamps are tested in conjunction with commercially available preheat controlgear (ballasts).

The rated average lamp life is the expected time at which 50% of any large number of lamps reach the end of their individual lives.

Actual operating conditions deviate in most cases from the applied test conditions. The differences can have a significant influence on lamp performance.

Switching cycle effects

The rated average lamp life of MASTER TL5 lamps is negatively affected when the switching frequency is higher than the IEC cycle (3 hrs cycle: 165 minutes on, 15 minutes off).

The table below gives an indication of the relation between the amount of switching and the lamp life.

Operating cycle time min	Rated average lamp life h	Lamp life	Switches nr.
660 on, 60 off	28.000	117%	2550
480 on, 30 off	27.000	113%	3380
165 on, 15 off	24.000	100%	8730
90 on, 15 off	22.000	92%	14.667
45 on, 15 off	19.000	79%	42.200

Note: Lifetime figures depend on ballast type. In practice lifetimes can deviate.


Extract of page 23 of “Philips Master TL5 lamps – February 2006” produced by Philips Lighting B.V.

Where standard Philips Master TL5 lamps are used, the VSPLAG recommends the following replacement cycles and failure details for these luminaires.:

- The recommended lamp replacement period for bulk changes is 4 years.
- The expected failures rate between bulk changes is 8.6% (average annual failure rate of 2.15%)

CF Lamp Failure Rates


Lamp Survival - Lynx 26W, 32W & 42W CFTE



Calculation of lamp life expectancy:


From the figure above, at 4 years (16644 hours), the survival rate of a CF lamp based on a 11 hr switching cycle is 85% or 15% failure rate (or $15/4 = 3.75\%$ per year average).

80W MV Lamp Failure Rates



Appendix 3 : Electronic (Ballast) Control Gear (ECG) Failures Rates

Life expectancy curve below².



Calculation of ECG life expectancy:

The table below summarises the expected life of the ECG at different maximum temperatures at the T_c point. Note that this is conservatively based on 3 hour switching cycle. It is expected that there will be increased life for 11 hr switching cycle (for lamps the life is increased by 17%). ECG life is dependent on maximum temperature.

Temperature	Failure rate at 8 Years	Failure rate at 12 Years	Failure Rate at 20 Years
50 °C	3%	5.5%	10.75%
60 °C	3%	5.5%	13.75%
70 °C	5.5%	13.75%	100%

It was noted that electronic control gear (such as the Osram used as standard for the Twin T5 luminaire) is sensitive to temperature. The higher the peak temperature over the life of the ECG the shorter that life is expected to be. It was noted that further research is required to determine the peak temperature at the “cool spot” (T_c) of the ECG over Summer periods in Victoria. It was further noted that the following information will be reviewed based upon the research determining peak summer T_c temperature.

- An expected max. temperature of 60 deg will give an expected failure rate of 5.5% at 12 years (equal to an average annual failure rate of 0.46%)
- The expected worst case max. temperature of 70 deg will give an expected failure rate of 5.5% at 8 years. (equal to an average annual failure rate of 0.69%)

² From Page 20 of “ECG for T5 fluorescent lamps - Technical Guideline May 2005” produced by Osram.

It was decided to adopt a bulk replacement at 8 years with a 5.5% failure rate before bulk changes - this will be reviewed based upon testing and in field failure in existing large scale trials. Further testing of ECG temperature will be carried out in an in field situation over the summer in 2007/8.

From Page 20 of “ECG for T5 fluorescent lamps - Technical Guideline May 2005” produced by Osram.

Appendix 4 : Information from Field Trials

The information from other trials includes the following (in order of appearance on the proceeding pages) :

1. Information on trials from Bill Harrigan (Integral Energy) dated Sept. 2007 and email dated 30 March 2007.
2. Report from Pierlite on the total failures for the Energy Australia trial (installed in 2003/4) and the reasons for each failure. The reports are from (1) A summary of all the issues from the trial establishment to September 2007 (2)February 2006 and (3)November 2006.
3. Report on AGL/NAGA sustainable public lighting trials

These reports immediately follow a summary and discussion of these reports, which is found below.

Integral Energy

Integral Energy has been instrumental in bringing this product to market. They went to the manufacturers and asked them to develop a more efficient light for Category P roadlighting. As a result Pierlite developed the 2x14W T5 Greenstreet.

At the time of writing this report there were between 7-8000 of the 2x14W and 2x24W T5's installed in Integral Energy's area. These were first installed in 2003. The Greenstreet is now the standard fitting for minor road lighting for 60% of Integral Energy's Councils.

Bill Harrigan, from Integral, has been involved in the program from the beginning and had this to say about the technology (see full email later in this Appendix):

"Apart from some early problems with the T5 luminaire itself we are not seeing any evidence of unsatisfactory lamp performance including survival rates with few failures to date.

We do recognise that at present the electronic control gear employed in the luminaire will not be as robust or last as long as the ferro-magnetic gear presently used.

We believe that the benefits of: longer lamp life, reduced losses, lower lumen depreciation and higher efficiency combined with stable light output under varying voltage conditions more than offset this."

Energy Australia

The Energy Australia trial started in 2004 where 1,000 T5 luminaires were installed. The table below describes the failures recorded up until the Sept. 2007 (i.e. 3 – 3.5 years installed). These failures are well within expected failures noted by manufacturers.

Reason for failure	Number	Action/Comment
General breakages (eg clips, lense etc.)	4	
Lamps not turned into holder properly	11	This was "an early production problem" – no further issues.
Lamps missing/failed	26	Worked after replacement. Manufacturers allow 2% per year.
PE cell base	3	New design reduces stress on base.
Ballast failed	4	
No fault	5	Cell installation fixed unit
PE cells	5	Cell replacement fixed unit

Total 58

NAGA and AGL

The NAGA and AGL trial also began in 2004. 120 lights were installed including 80 2x14W T5 Greenstreets. The program was a joint program between AGL and the Northern Alliance for Greenhouse Action (NAGA) comprising nine Councils in Melbourne's North.

Recently the final report on the trial was concluded. It should be noted that only small numbers of 42W cfls were trialled and this report is most appropriate for analysing the field performance of the 2x14W T5. The conclusion reads as follows:

“The AGL and NAGA trials tested the field and laboratory performance of energy efficient lights that can replace the existing 80 watt (W) Mercury Vapour (MV) technologies. The trial lights were:

- Pierlite Greenstreet 2x14W T5
- Sylvania Urban 50W High Pressure Sodium (HPS)
- Sylvania Suburban 42W Compact Fluorescent (CFL)

Pierlite Greenstreet 2x14W T5

Based on the results of these trials we recommend the use of the T5 as a standard direct replacement for the 80W Mercury Vapour. The T5 luminaire has an International Protection (IP) rating similar to other accepted luminaires. Maintenance is slightly increased which results in increased maintenance cost, because of two lamps and electronic control gear that may require periodic replacement.

Although unit cost is slightly increased in terms of maintenance and purchase the benefits of better uniformity of light across and along the street, better colour rendering and visibility, best current technology in terms energy performance, less lumen depreciation and lamp failure rate far outweigh the costs.

Sylvania Urban 50WHPS

Based on the results of these trials we do not recommend the use of the 50W HPS as a standard direct replacement for the 80W MV because of the reduced colour rendition and poor visibility to the human eye.

Sylvania Suburban 42W CFL

Based on the results of these trials we recommend the use of the 42W CFL as a direct replacement for the 80W MV only where 2x14W T5 cannot be used (e.g. some decorative streetlights).”

The following information was provided by Pierlite directly from correspondence from Bill Harrigan of Integral Energy.

Here is some feedback from Integral Energy about their experience with T5s to date that may be of use. If you have any questions about this, Bill Harrigan of Integral Energy can be reached at 4255 4021 or bill.harrigan@integral.com.au.

The questions posed to Integral and the responses are as follows:

- 1) **Approximately how many T5 luminaires have been installed in Integral Energy's service territory?** Pierlite estimate about 7000-8000 as of Sep 07 based on shipments to Integral Energy and ASPs (DB of Pierlite Sep 07). I am not sure of the exact total as it takes some considerable time from when a lantern is installed until it appears on our database (BH of Integral Sep 07)
- 2) **Of Integral Energy's 19 councils, how many have nominated the T5 as a current default luminaire?** The Greenstreet is the standard P category luminaire for residential type applications for several of our larger councils including: Liverpool, Fairfield, Campbelltown, Penrith , Blacktown & Blue Mountains. More councils are asking that the Greenstreet become their preferred luminaire. About 60 % of new developments are in these areas (BH Sep 07)
- 3) **Since MOVs were introduced in 2004, how many ballast failures has Integral Energy reported?** Very few, only 5 reported (BH Mar 06) The number of failures since MOV's has been low but I don't have numbers. (BH Sep 07)
- 4) **Is Integral satisfied with the overall design and construction of the luminaire?** Yes but would like to see a simpler way to replace control gear. (BH Sep 07)
- 5) **Have Integral experienced any difficulty in maintenance, such as lamp changes?** No (BH Mar 06)
- 6) **Have Integral noted any problems with gaskets, seals or clips?** The only problem we have had is with the gear compartment cover, which was not well retained on early models We still have some problems with the retention of the gear compartment cover but I don't know if it is happening on current version. (BH Sep 07)
- 7) **Experience with lamp failures?** We have had very few lamp failures to date. T5 as a lamp type is very reliable, there is no reason to query the data supplied by the manufacturers based on the sample sites so far. (BH Mar 06)
- 8) **Have there been any customer complaints about the T5 luminaire, for problems such as glare?** None that I know of (BH Mar 06) We have had a few glare complaints but this is normal for the number of lanterns installed. (BH Sep 07)

Paul Brown

From: Bill Harrigan [Bill.Harrigan@integral.com.au]
Sent: Friday, 30 March 2007 9:46 AM
To: Paul Brown
Subject: RE: T5 experience
Attachments: Mercury lamp performance.xls

Hi Paul,
Further to our phone conversation concerning the performance of our T5 Greenstreet luminaires:

- It is true that it takes a little more time to change the lamps in the T5 than more conventional luminaires however this has very little impact on overall maintenance costs. The lamp change appears to take around 60 to 90 seconds longer which is a very small increased cost over our 3 year group replacement cycle.
- We currently use a 3 year lamp replacement period on 80watt mercury as we don't believe that we can comply with the requirements of AS1158 in terms of light output from the lamp when lumen maintenance, luminaire depreciation and the fact that the lamp is "under run" on 250 volt gear are taken into account if we used a longer period.(see attachment)
- It is too early for us to determine an economic group replacement interval for the T5 at this stage as we have insufficient data. We are naturally hopeful of achieving a longer cycle.
- Apart from some early problems with the T5 luminaire itself we are not seeing any evidence of unsatisfactory lamp performance including survival rates with few failures to date.
- We do recognise that at present the electronic control gear employed in the luminaire will not be as robust or last as long as the ferro-magnetic gear presently used. We believe that the benefits of:
longer lamp life, reduced losses, lower lumen depreciation and higher efficiency combined with stable light output under varying voltage conditions more than offset this.

If you have any further questions please don't hesitate to contact me.

Regards

Bill Harrigan
02 4255 4021

Please consider our environment before printing this email.

NOTICE - This communication contains information which is confidential and the copyright of Integral Energy Australia or a third party.

If you are not the intended recipient of this communication please delete and destroy all copies and telephone Integral Energy on 131081 immediately. If you are the intended recipient of this communication you should not copy, disclose or distribute this communication without the authority of Integral Energy.

Any views expressed in this Communication are those of the individual sender, except where the sender specifically states them to be the views of Integral Energy.

Except as required at law, Integral Energy does not represent, warrant and/or guarantee that the integrity of this communication has been maintained nor that the communication is free of errors, virus, interception or inference.

Summary of returns from EA received from batch of 1000 supplied in 2003/4.

A total of 56 have been received back, examined and faults logged. Separate reports have been supplied in the past in detail regarding our findings. Fittings were all examined and returned to EA. Faults were found in the categories defined in the categories below , and the following comments are made with respect to each item . We have allocated 1 primary fault to each fitting return, this fault being what we believe was the prime cause of the failure.

PE Cell

Out of 56, 51 were returned without cell. In 5 luminaires with cells, these were faulty and the lights worked when cell replaced. Faulty cells from Royce Thompson in the 1st batch supplied were prone to cycling and catastrophic failure which caused some early lamp failures through frequent switching .

Lamps

Of 56 returns 26 have worked when lamps replaced. Failures all appear to be in line with expected failure rates Philips and Osram claim 2% failure per 5000 hours. For 1000 fittings over 3 years this would be approx 50. We therefore have lower than expected lamp failure rates. In addition we have reasonable grounds to believe that the faulty cells mentioned earlier have caused several of the failures .

Ballast

In total we have 4 ballast failures . We have been unable to confirm a cause as there is no visible signs of damage. There is a good chance that moisture caused a short of 2, there was a clip missing and water in the lens of 2 of the luminaires where a faulty ballast was found. Ballast failure rates are less than predicted, indicating our thermal modelling predictions in 2003 have so far been accurate. The ballast operates in a cool environment usually at least 30 deg C below it's rated maximum, providing optimum conditions for longer life.

Lens clips

These were missing from 2 fittings, we are uncertain to the cause. Early model clips were fixed by rivet and used weaker steel springs. New clips now used are more robust.

Cell base

On 3 lights the cell base had broken, causing a short. The new design at the connection chamber allows better access and therefore less stress on the base when cells are changed. We believe that the cell failures meant that cells were changed often several times. Our design of the connection chamber cover has been modified to allow easier cell removal and to avoid stress on the base.

Damaged lens

2 lights were returned with damaged lens which may have been caused by vandalism or other impact.

Assembly errors

The 1st batch of 500 were prone to luminaire assembly 'teething' problems. 11 of the 56 had assembly errors , mainly incorrect lamp rotation. The lamp was not rotated correctly and starting therefore intermittent. This also would cause arcing at the lamp pins which would shorten life. Assembly procedures were changed as soon as problems identified. We have since made over 10,000 pieces and our largest customer Integral Energy has recently confirmed that there are no on-going quality issues. The product has been improved and assembly methods changed accordingly to allow larger volumes to be made.

No Fault

5 of the lights returned were found to have no cell, but worked when a new cell was inserted.

PIERLITE COMMENTS

If early assembly errors (11) , clip (2) PE Base (3) and No fault (5) are PE Cell (5) are considered problems that are either now rectified or not likely to occur again, this leaves 4 ballast failures and 26 lamp failures as the simplified mechanical/electrical breakdown. Both these failure rates are well below expected rates of failure. These are as experienced from other locations we have been monitoring.

For comment please contact David Blackley-97949300

QUALITY ASSURANCE REPORT

Catalogue: GS214ME4P
 Contact/Rep: SIMON ORGILL
 Customer: ENERGY AUSTRALIA
 Our Reference: PFR

Quantity Received: 17
 Date Received: Feb1st 2006
 Location: NSW
 Customer Reference:

EA #	Comment	Diffuser Clip	Lamps	Ballast	Diffuser	PE cell
14	No other fault	missing clip			Broken lens,	missing
15	No other fault		Lamps not fully turned into holder Assembly operators advised to ensure turn of tube is adequate			
16	No other fault		Lamps not fully turned into holder Assembly operators advised to ensure turn of tube is adequate			
17	No fault found					

18	Worked after wiring connection fixed		Both lamps missing	Loose connection at t/block		
19		Broken clips some leakage		Moisture inside caused ballast short		
20	No other fault found		Lamps not fully turned into holder Assembly operators advised to ensure turn of tube is adequate			
21				Failed Engineering unable to determine cause		
22	Ballast worked ok	2 clips missing	Both lamps missing			
23	No fault found					
24	No other fault found	missing	Lamps blackened but worked ok			
25	No other fault found		Lamps not fully turned into holder Assembly operators advised to ensure turn of tube is adequate			
26	No other fault found				Broken lens	
27	No other fault found		Lamps not fully turned into holder Assembly operators advised to ensure turn of tube is adequate			
28	No fault found					

29	No other fault found		1 Lamp failed			
30	No other fault found	missing	Lamps not fully turned into holder Assembly operators advised to ensure turn of tube is adequate		Broken lens	

Comments and summary

A total of 17 have been received back and logged. Fittings have been examined and will be returned EA. Faults were found in the categories defined in the chart above, and the following comments are made with respect to each item

Cell base.

All but one were returned without cell. No specific faults can be attributed to cells or bases.

Diffuser clip

Some clips missing but this may be due to shipping / transit. Some signs that missing clips caused leakage in 19, maybe others. In early batches supplied the clips were made using a more labour intensive operation. This increased risk of greater tolerances. With increased production volumes tooling was automated and quality improved. Further improvements will be made. QA checks are made to ensure current production is acceptable.

Lamps

Failures all appear to be in line with expected failure rates. Philips and Osram claim 2% failure per 5000 hours. For 500 fittings over 1 year we would expect maybe 10 failures. As there have been other issues effecting lamps-faulty cells, and assembly problems it is a little difficult to confirm this, however the rate is certainly not higher than this, and Integral have experienced rates below this. MV lamps have published failure rates roughly double this, so we would expect that lamp failures experienced so far would be more than acceptable.

More significant are failures due to incorrect assembly. With lamps only partially turned in the holders the lamp will operate, but a vibration could make the lamp move and break contact. Production line testing for later batches made of the 1000 has eliminated this problem.

Ballast

Two ballasts from this batch will be returned to Osram for testing, we are unable to confirm a cause as there is no visible signs of damage. Moisture or a short could be the causes. There is a small failure rate through life, given by suppliers as 1% per 1000 hours. This would be achieved at max operating temperatures however we are operating in most cases at least 20 deg below. We believe this will provide a failure rate at 0.5% per 1000 hours. For 500 fittings over a year this would mean maybe 10 fittings worst case. We are experiencing less than this. Our experiences with Integral also show we are achieving less than this. Longer running tests show minimal ballast failure rates on MOV protected fittings.

Diffuser

Difficult to say whether damage was caused in transit or on poles in most cases. On complete fittings no apparent signs of wear and tear, fading, or gasket damage.

• Page 3

General

It appears poor lamp insertion would be the cause of most of these faults. If fittings were removed subsequent physical damage is likely to have been caused then.

3 fittings worked when we powered them up, with no other adjustment, cells may have been a problem in these cases, but as cells were not returned we cannot speculate.

For comment please contact David Blackley-97949300

Compiled by: Ju Mei Li	Technical Quality Officer	Date: 1 st Feb 2006
Authorised by: Alan Shardlow	Quality System Co-ordinator	Date:

QUALITY ASSURANCE REPORT

Catalogue: GS214ME4P Quantity Received: 12 Date Received: Nov 2006
 Contact/Rep: Location: NSW
 Customer: ENERGY AUSTRALIA Customer Reference:
 Our Reference: PFR

EA #	Comment	Date of manufacture	Lamps	Ballast	Diffuser	PE cell
30	No other fault	May 2004				missing
31	Worked after installing cell and new lamps	May 2004	Lamps darkened at one end, not working			missing
32	No fault found	May 2004				
33	No other fault found	May 2004	Lamps darkened at one end, but worked			
34	Worked after installing cell	May 2004				missing
35	Worked after installing cell	Sept 04	Lamps darkened at one end, but worked			missing
36	Worked after installing cell	Sept 04	Lamps darkened at one end, but worked			missing
37	Worked after installing cell- corrosion see below	May 2004	Lamps darkened at one end, but worked			Cell returned but faulty
38	Worked after installing cell and Ballast	May 2004	Lamps darkened at one end, but worked after ballast replaced	Ballast failed, possibly due to cell failure		Cell returned but faulty
39	Worked after installing cell	May 2004	Lamps darkened at one end, but worked after cell replaced			Cell returned but faulty

40	Worked after installing cell and new lamps	May 2004	Lamps darkened at one end, not working			missing
19	Worked after installing cell and new lamps	May 2004	Lamps darkened at one end, not working			Cell returned but faulty

Comments

A total of 12 have been received back and logged on this report. Fittings have been examined and will be returned to EA. Faults were found in the categories defined in the chart above, and the following comments are made with respect to each item

Cell

6 were returned without cell, so it is reasonable to assume the cell had failed in the field. On 4 of the 6 with missing cells, lamp ends had darkened, but 4 of the 6 were still working when cell replaced.

Of the remaining 6 with cell, 4 had faulty cells. Of these 5 worked when new cells were fitted.

Lamps

Failures all appear to be in line with expected failure rates. Philips and Osram claim 2% failure per 5000 hours. For 500 fittings over 1 year we would expect maybe 10 failures. Faulty cells have caused several of the failures. Increased lamp end blackening does occur with T5. This is due to the material from the cathodes being deposited on the glass of the tube being more noticeable on the smaller lamps than with T8 lamps. They operate satisfactorily with no loss of performance.

Ballast

One ballast from this batch will be returned to Osram for testing, however it is unlikely we will be able to confirm a cause as there is no visible signs of damage. Moisture or a short could be the cause

Corrosion on body #37

Our earlier body type had occasional flow problems within the tool. This caused a small patch to cool on the tool earlier than the main flow. This has lead to 'peeling', as this indicates. It is not caused by material weakness or copper content. The tool modifications made since 2004 have eliminated this problem.

General

It appears poor quality cells would be the cause of most of these faults. As 50% of the fittings were supplied without cells we cannot determine the exact nature of the failure. 9 of the fittings worked when cell was replaced.

For comment please contact David Blackley-97949300

Compiled by: Amy Zhang	Technical Quality Officer	Date: 26th Nov 2006
Authorised by: Alan Shardlow	Quality System Co-ordinator	Date:

Appendix 5 : Maintenance Factor Determination

The Maintenance Factor is the product of the Luminaire Maintenance Factor (LMF) and the Light Loss Factor (LLF). The LLF is also known as the Lamp Lumen Depreciation Factor: Therefore
 $MF = LMF \times LLF$

The Lamp Lumen Depreciation Factors used in these calculations have been interpolated from Lumen Depreciation Curves supplied by the various Lamp Manufacturers

	Initial lumens	Energy use (W)	Initial lm/W	4 year lm/W	Lumen Depreciation factor	4 year luminaire maintenance factor	4 Year Maintenance factor
80W MV - B2224	3800	96	39.6	26.1	66%	0.76	0.50
80W MV - Urban	3800	96	39.6	26.1	66%	0.84	0.55
2x14W T5	2400	30.5	78.7	70.8	90%	0.84	0.76
2x24W T5	3500	47	74.5	67.0	90%	0.84	0.76
26W CFL	1800	28	66.7	53.4	80%	0.84	0.67
32W CFL	2400	34	64.9	51.9	80%	0.84	0.67
42W CFL	3200	44	72.7	58.2	80%	0.84	0.67
50W HPS	3300	61.7	53.5	38.5	90%	0.84	0.76

Appendix 6: Lumen depreciation with temperature

High Intensity Discharge Lamps (HID), such as MV or HPS types can operate within a very wide range of ambient temperatures. Fluorescent lamps however are more temperature dependent.

The issues of interest include whether the T5 lamps will start in cold temperature and the impact on light output from these low temperatures.


Starting

Light output vs time tests were carried out on a twin 14W T5 luminaire with non-amalgam lamps for ambient temperatures down to -5°C (see curve below) with successful lamp starting at all temperatures down to -5°C .

Noting that the lamps start at between 4pm and 6pm in Winter (close to the peak temperature for any given location at that time) it is unlikely that starting will be a problem for any T5 luminaires in Australia. Further information on start up temperature performance of the T5 lamps has been provided by Pierlite and is provided in *Appendix 7*.

Light depreciation in low temperatures

Light output vs time tests were performed on a twin 14W T5 luminaire with non-amalgam lamps for ambient temperatures down to -5°C (see curve below) with results showing that after about 30 minutes from lamp startup, there was little variation in light output eg after 30 minutes from statup, there is a 7% drop in light output between outputs at 0°C and 20°C and a 12% drop in light output between outputs at -5°C and 20°C .



A similar test was performed on a 42W CF with an amalgam lamp (see curve above) with the result that after 15 minutes there was little difference in light outputs over the ambient temperature range of 20°C to -5°C .

Also, the on-site measurements of trial areas of 2x14W T5 luminaires with non-amalgam lamps over the past three years have shown that there has been no significant difference between Summer and Winter illuminance readings once the luminaires have fully warmed up.

At Viewbank (a middle suburb of Melbourne) the coldest temperature measured over a 5 year period was -1.1°C . The temperature measured under 0°C less than 0.1% of the time.

Site	Viewbank	Falls Creek
Time	2002-7	2002-7
Coldest temperature in period	-1.1	-8.5
Number of days under 0°C	20	767
Average hours under 0°C on these days	2.1	14.1
% of time under 0°C	0.095%	24.623%
Number of days under 5°C	201	
Average hours under 5°C on these days	3.7	

In Falls Creek (one of the coldest places in Victoria) the temperature remained under 0°C almost 25% of the time and reached a coldest temperature of -8.5°C.

The spacing table below (based on light outputs after 4 years of service taking into account lumen depreciation and maintenance factors) was produced using T5 non-amalgam lamp light levels at 0°C (a 7% drop in output from the 20 °C level) & -5°C (a 12% drop in output from the 20 °C level) to compare the light spacings with 80W MV lights.

Category P5 Lighting		
7.5m Mounting Height	15m road reserve	20m road reserve
80W MV (Urban)	82m	78m
80W MV (B2224)	76m	74m
T5 twin 14W (at 0°C)	82m	80m
T5 twin 14W (at -5°C)	80m	78m

This information shows that even at 0°C & -5°C the T5 luminaire with non-amalgam lamps will generally perform to a similar or better standard than the 80W MV either in the Urban (the new style of luminaire) or the B2224 (the older style that is by far currently the largest installed by volume).

For any new installations, designs should take into account the implications of extremely low temperatures. However, it is recommended to make designs easier by utilising the amalgam lamp as the standard 14W T5 lamp when it becomes available.

Appendix 7 : T5 Temperature Start-up Test



Pierlite Pty Ltd
ABN 62 008 173 359
96 – 112 Gow Street, Padstow
PO Box 314, Padstow
New South Wales 2211
Telephone +61 2 9794 9300
Facsimile +61 2 9707 4190
E-mail lighting@pierlite.com.au
Internet www.pierlite.com.au

Laboratory Report

No. PLR0129

Product: Green street luminaire
Manufacturer: Pierlite P/L
Test Type: Cold start test
Result: refer below
Date: 17-5-05

A 2x 24W Green Street luminaire was placed within the engineering freezer and left over a period of 48 Hrs in the off state, the freezer temperature dropped down to -15°C.

The GS224 luminaire had power applied to it after the 48Hrs were it switched on at - 15°C, the following ambient also tested without any delays in switch on,(note light levels were not measured in this test).

Temperature	Switch on
-5°C	√
-10°C	√
-15°C	√

the test ended at -15C were the freezer could not drop the ambient any further.



Photo of Green Street in freezer
After testing.

George Ebejer
Senior Electrical Testing Engineering

Appendix 8 : Inputs into OMR Prices

The following data can be used to input into the ESC Public lighting OMR model.

	Pierlite T5	Sylvania CF
Depreciation Period – luminaire body	20 years	20 years
Lamps - bulk change	Every 4 years	Every 4 years
PE cell – bulk change	Every 8 years	Every 8 years
Gear Tray – bulk change	Every 8 years	Every 8 years
Proportion of lamps that fail between bulk changes	8.6%	14%
Proportion of Gear trays (ECG's) that fail between bulk changes	5.5%	5.5%

Appendix 9 : Approved Manufacturing Drawings

Pierlite T5

© COPYRIGHT: THIS DRAWING IS OWNED BY PIERLITE PTY. LTD. ON THE UNDERSTANDING THAT IT IS STRICTLY CONFIDENTIAL AND MAY NOT BE REPRODUCED IN ANY WAY WITHOUT PRIOR PERMISSION.

LENS GREENSTREET CLEAR ACRYLIC
99013630
PUSH ON FIX 4MM
99001004
BAFFLE GREENSTREET MIRO 4
99013636

COVER GREENSTREET TERMINAL NEW
99004476- SUPPLIED SEPARATELY
COVER PLUG GREENSTREET PE CELL
99004477

SCREW M3 x 10 PAN POZI PT SS
99009308
WASHER M4 FLAT SS
95031022
WIRE GREENSTREET LENS RETAIN
99009078

T5 LAMP
14W - PHILIPS MASTER T5 HE 14W/840
24W - OSRAM FO 24W/840 HO CONSTANT FLH1

L/HOLDER T5 8JB 26.620.2104.S0
99021101 (WITH STOP)

REFLECTOR GREENSTREET MIRO 4
C/W LABEL RE: TUBE INSTALLATION
99002991

LABEL
(LAMP LABELS THIS END ONLY)

ELECTRONIC BALLAST VOSSLOH
14W - 2 X14/21/28/35W
24W - 2 X24/39/49/54/80W

L/HOLDER T5 VOSSLOH 09421 505739.01
99002538 (WITHOUT STOP)

GEARTRAY GS14/24W POLYCARB
99004488

PHOTO CELL - SELCON KAGA 2 AMP D2
95004030

SCREW M8 x 30 SS HEX HD
99003535

NUT M8 SS LOCKNUT
99011386

CLIP GREENSTREET REAR SPRING
99020981

VARIATOR MYG20-S11A
99004226

TERMINAL BLOCK 3W PLASTIC 25A 4.1 BOR
95022012

PLATE TERMINAL PE NEW GREENSTREET P/C
99020624

3 WAY TERMINAL SOCKET MALE

3 WAY TERMINAL SOCKET FEMALE

BODY GREENSTREET W/CLIPS NEW
99004479

CLIP GREENSTREET FRONT SPRING
99020980

BASKET GREENSTREET 5MM DIA
99002731

GROMMET A5 12.7MM
99002407

SCREW M5 x 8 PH PAN HD SS
95030049
WASHER M5 INT SHK PRF SS
95031081

CABLE CLAMP LOCATION

SUPPLY TERMINALS

GEAR TRAY TERMINALS

197.7

112.1

764.8

PE CELL LOCATION

HINGES ON THIS SIDE

NOTE:
1. NOT ALL COMPONENT DESCRIPTIONS AND PART NUMBERS SHOWN PLEASE REFER SYSTEM BOM'S
2. TO BE FREE FROM BURRS AND SHARP EDGES.

DESTROY ALL PREVIOUS ISSUES

Dimensions in millimeters. Do not scale.

PIERLITE 14-12 Gow Street Tel: 03 9794 9900
Franklin Rd W211 Fax: (03) 979 8225

GREENSTREET
GREEN STREET VICTORIA SPEC.

STATUS: FINAL

DRAWN: BAIV **DATE:** 7/12/2007

CHECKED: BELY CHU **DATE:** 7/12/2007

PART No: GS214VIC/P, GS224VIC/P **DRG. No.:** C6003

BY: DATE: 14/03/2008 **SHE. 1 OF 1** **ASSY. change** **PR 0** **SCALE:** 1:3 **AZ**

REV.	DESCRIPTION	ECN	DATE	APPROVED
2	PART NO. FOR 24W VERSION ADDED.		28/02/2008	
1				