



REFERENCE MARKS

Stn	To	Bearing	Dist	Origin
2	Nail in Bitumen Fd	312°22'40"	9.042	
2	Screw in Conc	186°52'30"	7.532	
3	Nail in Bit Fd	289°44'50"	10.314	
3	ONail in Chan Gane	265°48'15"	11.761	SPI40762 DPI28890
9	ONail in Conc Gane	171°29'50"	28.754	
10	Screw in Conc	123°23'40"	5.861	
10	Screw in Conc	238°27'	14.931	
11	ONail in Kerb	298°04'30"	15.028	RP891235 RP891235
12	OScrew in Conc	336°36'15"	1.731	
14	ONail in Bitumen	211°22'	9.875	IS193482

Not Srech

No O Mk, No Mk Pld at Stns 4-8

Note: Leases C-H are located on the rooftop of the building and are shown on CT 50099062
Dated: 23rd September 2013

Scale 1:500 Lengths are in Metres



Client: INCITE

HILLMIR Pty Ltd (A.B.N. 75 009 728 634) (t/a Goodwin Midson) hereby certify that the land comprised in this plan was surveyed by the corporation, by David John WICKS Surveying Associate, for whose work the corporation accepts responsibility, under the supervision of Alistair BYROM, Cadastral Surveyor and that the plan is accurate, that the said survey was performed in accordance with the Survey and Mapping Infrastructure Act 2003 and Surveyors Act 2003 and associated Regulations and Standards and that the said survey was completed on 9/10/13

Alistair Byrom
Director
Cadastral Surveyor

Date: 9/10/2013

GOODWIN MIDSON
SURVEYING | TOWN PLANNING | MAPPING

Servicing Queensland with offices in:
BRISBANE (07) 3670 2161
BOONAH (07) 5463 1596
SUNSHINE COAST (07) 5493 1707
HERVEY BAY (07) 425 1855
www.goodwinmidson.com.au

Plan of Identification Survey of Lot 5 RP891235

PARISH NORTH BRISBANE
COUNTY Stanley
LOCALITY FORTITUDE VALLEY
LOCAL GOV BRISBANE CITY COUNCIL

ORIGINAL: ESA.7
Meridian: MGA
vide IS193482
Map Reference: 9543-333/3
Scale: 1:500
Job Number: 9337
Title Reference: 50099062



IS250565

This plan is of an Identification Survey ONLY and as such should be used only for the purpose for which it was prepared. Owners or purchasers should be aware that if utilising or building to the boundary, the author of the plan or consulting surveyor of choice should be first contacted in case boundary locations on this or adjoining lots carries higher than normal risk. Goodwin Midson therefore can accept no responsibility for failure to use this plan within the limitations intended.