



INSPECTION CHECKLIST FOLLOWING COMPLETION OF RURAL VEGETATION CLEARING WORK

Location: Willow	/ale Home stead	Date: August 9 2013	Inspected, by:		
Company:					
NCR required for Non Co	onformances YES/NO	If Yes Process owner is	NCR #		
On Site Documentation 1. Has clearing work been done in accordance with the instructions in the WP?	Assessment Acceptable	Comments	Action Required/Completed	By Who	Due Date
2. Has the Contractor done the clearing work in accordance with the instructions given to the Contractor?	Acceptable				
3. Is the Land Manager satisfied with work done	Acceptable Acceptable	Owner happy with the work completed and the polite attitude of the crew			

Reference documents:

- 1. Work Safety regulation 2011
- 2. ASNZS 1269 Occupational noise management Measurement and assessment of noise emission and exposure);
- 3. Code of practice First Aid
- 4. Guidance material for Traffic Risk Management Guide to Horticulture and Cleaning Industries
- 5. ActewAGL (electrical Rule Book) Blue Book
- 6. ActewAGL Standing Offer No.095/10





- 7. ActewAGL Procedure EN 4.2 P 12
- 8. ActewAGL Procedure EN 4.2 P 15

Inspector Comments

Owner happy with the work completed and the polite attitude of the crew





INSPECTION CHECKLIST FOLLOWING COMPLETION OF RURAL VEGETATION CLEARING WORK

Location: Bendora Dam Date: May 16 2012 Inspected, by:							
Company:							
NCR required for Non Conformances YES/NO If Yes Process owner is NCR #							
On Site Documentation	Assessment	Comments	Action Required/Completed	By Who	Due Date		
1. Has clearing work been done in accordance with the instructions in the WP?	☐ Acceptable						
2. Has the Contractor done the clearing work in accordance with the instructions given to the Contractor?	Acceptable						
3. Is the Land Manager satisfied with work done	Acceptable						

Reference documents:

- 1. Work Safety regulation 2009
- 2. Work Safety Act 2008.
- 3. ASNZS 1269 Occupational noise management Measurement and assessment of noise emission and exposure);
- 4. Code of practice First Aid





- 5. Guidance material for Traffic Risk Management Guide to Horticulture and Cleaning Industries
- 6. ActewAGL (electrical Rule Book) Blue Book
- 7. ActewAGL Standing Offer No.095/10
- 8. ActewAGL Procedure EN 4.2 P 12
- 9. ActewAGL Procedure EN 4.2 P 15

Inspector Comments Job site was left in a very good neat and safe state.

All works were completed correctly and all staff members should be congratulated on their efforts





INSPECTION CHECKLIST FOLLOWING COMPLETION OF RURAL VEGETATION CLEARING WORK

Location: Uriarra	a Village Pole 832	292 Date: 08 October 2012	Inspected, by:					
Company:								
NCR required for Non Conformances YES/NO If Yes Process owner is NCR #								
On Site Documentation 1. Has clearing work been done in accordance with the instructions in the WP?	Assessment Needs Attention	Good clearance from HV lines but clearance needs to be all branches heading towards power lines to ground level	Action Required/Completed Lower branches under HV need to be removed (refer to photo below)	By Who have being informed of works required	Due Date End of August			
2. Has the Contractor done the clearing work in accordance with the instructions given to the Contractor?	□ Needs Attention	<u>As Above</u>	<u>As Above</u>	<u>As Above</u>	As Above			
3. Is the Land Manager satisfied with work done	NA							







Comments

have being informed of the works needed to complete work on this tree. All other work inspected on Cotter feeder, is to ActewAGL standard



ActewAGL

Electricity Networks HSE Management System

Reference documents:

- 1. Work Safety regulation 2009
- 2. Work Safety Act 2008.
- 3. ASNZS 1269 Occupational noise management Measurement and assessment of noise emission and exposure);
- 4. Code of practice First Aid
- 5. Guidance material for Traffic Risk Management Guide to Horticulture and Cleaning Industries
- 6. ActewAGL (electrical Rule Book) Blue Book
- 7. ActewAGL Standing Offer No.095/10
- 8. ActewAGL Procedure EN 4.2 P 12
- 9. ActewAGL Procedure EN 4.2 P 15

Inspector Comments





INSPECTION CHECKLIST FOLLOWING COMPLETION OF RURAL VEGETATION CLEARING WORK

Location: Glenlo	ch Farm D	Date: August 8 2013 Inc	spected, by:				
Company:							
NCR required for Non Conformances YES/NO If Yes Process owner is NCR #							
On Site Documentation	Assessment	Comments	Action Required/Completed	By Who	Due Date		
1. Has clearing work been done in accordance with the instructions in the WP?	Acceptable	Works completed to ActewAGL standards					
2. Has the Contractor done the clearing work in accordance with the instructions given to the Contractor?	Acceptable	Contractor followed instructions fully					
3. Is the Land Manager satisfied with work done	☐ Acceptable	Land owner very happy with work completed					

Reference documents:

- 1. Work Safety Act 2011.
- 2. ASNZS 1269 Occupational noise management Measurement and assessment of noise emission and exposure);
- 3. Code of practice First Aid
- 4. Guidance material for Traffic Risk Management Guide to Horticulture and Cleaning Industries
- 5. ActewAGL (electrical Rule Book) Blue Book
- 6. ActewAGL Standing Offer No.095/10





- 7. ActewAGL Procedure EN 4.2 P 12
- 8. ActewAGL Procedure EN 4.2 P 15

<u>Inspector Comments</u> Contractor completed work was to a very high standard





INSPECTION CHECKLIST FOLLOWING COMPLETION OF RURAL VEGETATION CLEARING WORK

Location: Bruce Z	one to Belconnen	Zone Date: 24 January 2	2012 Inspected, by:		
Company:					
-					
NCR required for Non C	onformances YES/NO	If Yes Process owner is	NCR #		
On Site Documentation	Assessment	Comments	Action Required/Completed	By Who	Due Date
1. Has clearing work been done in accordance with the instructions in the WP?	Needs Attention	Stumps of some trees that were removed were left too high and not cut level to the ground level. Some cut vegetation left on site and some dead trees left standand	Stumps to be cut lower to the ground and level to the ground not at an angle. Any cut vegetation that was left on site to be removed. Dead wood left standing to be removed		Befor the issue of any futhur works
2. Has the Contractor done the clearing work in accordance with the instructions given to the Contractor?	Needs Attention	<u>As above</u>	<u>As above</u>	<u>As above</u>	<u>As above</u>
3. Is the Land Manager satisfied with work done	Needs Attention	<u>As above</u>	<u>As above</u>	As above	As above

Reference documents:

- 1. Work Safety regulation 2009
- 2. Work Safety Act 2008.
- 3. ASNZS 1269 Occupational noise management Measurement and assessment of noise emission and exposure);





- 4. Code of practice First Aid
- 5. Guidance material for Traffic Risk Management Guide to Horticulture and Cleaning Industries
- 6. ActewAGL (electrical Rule Book) Blue Book
- 7. ActewAGL Standing Offer No.095/10
- 8. ActewAGL Procedure EN 4.2 P 12
- 9. ActewAGL Procedure EN 4.2 P 15

Inspector Comments

can you please have a look at the works that have being undertaken on this feeder and are not up to standard and rectify





INSPECTION CHECKLIST FOLLOWING COMPLETION OF RURAL VEGETATION CLEARING WORK

Location: Fairley	feeder Date:	March 2013 Inspected	d, by:				
Company:							
NCR required for Non Conformances YES/NO If Yes Process owner is NCR #							
On Site Documentation	Assessment	Comments	Action Required/Completed	By Who Due Date			
1. Has clearing work been done in accordance with the instructions in the WP?	Acceptable						
2. Has the Contractor done the clearing work in accordance with the instructions given to the Contractor?	Acceptable						
3. Is the Land Manager satisfied with work done	☐ Acceptable						

Reference documents:

- 1. Work Safety regulation 2009
- 2. Work Safety Act 2008.
- 3. ASNZS 1269 Occupational noise management Measurement and assessment of noise emission and exposure);
- 4. Code of practice First Aid





- 5. Guidance material for Traffic Risk Management Guide to Horticulture and Cleaning Industries
- 6. ActewAGL (electrical Rule Book) Blue Book
- 7. ActewAGL Standing Offer No.095/10
- 8. ActewAGL Procedure EN 4.2 P 12
- 9. ActewAGL Procedure EN 4.2 P 15

Inspector Comments

All works completed to ActewAGL standards 100% inspected





INSPECTION CHECKLIST FOLLOWING COMPLETION OF RURAL VEGETATION CLEARING WORK

Location: Monaro	feeder	Date:	February	2013	Inspecte	d, by:			
Company:									
NCR required for Non Conformances YES/NO If Yes Process owner is NCR #									
On Site Documentation 1. Has clearing work been done in accordance with the instructions in the WP?	Assess Acceptable			Comments		Action Req	uired/Completed	By Who	Due Date
2. Has the Contractor done the clearing work in accordance with the instructions given to the Contractor?	Acceptable	le							
3. Is the Land Manager satisfied with work done	Acceptable	le							

Reference documents:

- 1. Work Safety regulation 2009
- 2. Work Safety Act 2008.
- 3. ASNZS 1269 Occupational noise management Measurement and assessment of noise emission and exposure);
- 4. Code of practice First Aid





- 5. Guidance material for Traffic Risk Management Guide to Horticulture and Cleaning Industries
- 6. ActewAGL (electrical Rule Book) Blue Book
- 7. ActewAGL Standing Offer No.095/10
- 8. ActewAGL Procedure EN 4.2 P 12
- 9. ActewAGL Procedure EN 4.2 P 15

Inspector Comments

All works completed to ActewAGL standards 100% inspected





INSPECTION CHECKLIST FOLLOWING COMPLETION OF RURAL VEGETATION CLEARING WORK

Location:Mugga Fe	eder Date:	March 2013	nspected, by:						
Company:	Company:								
NCR required for Non Conformances YES/NO If Yes Process owner is NCR #									
On Site Documentation 1. Has clearing work been done in accordance with the instructions in the WP?	Assessment Acceptable	Comme	nts A	Action Required/Completed	By Who	Due Date			
2. Has the Contractor done the clearing work in accordance with the instructions given to the Contractor?	Acceptable								
3. Is the Land Manager satisfied with work done	Acceptable								

Reference documents:

- 1. Work Safety regulation 2009
- 2. Work Safety Act 2008.
- 3. ASNZS 1269 Occupational noise management Measurement and assessment of noise emission and exposure);
- 4. Code of practice First Aid





- 5. Guidance material for Traffic Risk Management Guide to Horticulture and Cleaning Industries
- 6. ActewAGL (electrical Rule Book) Blue Book
- 7. ActewAGL Standing Offer No.095/10
- 8. ActewAGL Procedure EN 4.2 P 12
- 9. ActewAGL Procedure EN 4.2 P 15

Inspector Comments

All works completed to ActewAGL standards 100% inspected





INSPECTION CHECKLIST FOLLOWING COMPLETION OF RURAL VEGETATION CLEARING WORK

Location: Newcastle Feeder Date: March 2013 Inspected, by:								
Company:								
NCR required for Non Co	onformances YES/	NO If Yes Process owner	is	NCR #				
On Site Documentation	Assessment	Comments	Action Re	equired/Completed	By Who	Due Date		
1. Has clearing work been done in accordance with the instructions in the WP?	Acceptable							
2. Has the Contractor done the clearing work in accordance with the instructions given to the Contractor?	Acceptable							
3. Is the Land Manager satisfied with work done	☐ Acceptable							

Reference documents:

- 1. Work Safety regulation 2009
- 2. Work Safety Act 2008.
- 3. ASNZS 1269 Occupational noise management Measurement and assessment of noise emission and exposure);
- 4. Code of practice First Aid





- 5. Guidance material for Traffic Risk Management Guide to Horticulture and Cleaning Industries
- 6. ActewAGL (electrical Rule Book) Blue Book
- 7. ActewAGL Standing Offer No.095/10
- 8. ActewAGL Procedure EN 4.2 P 12
- 9. ActewAGL Procedure EN 4.2 P 15

Inspector Comments

All works completed to ActewAGL standards 100% inspected





INSPECTION CHECKLIST FOLLOWING COMPLETION OF RURAL VEGETATION CLEARING WORK

Location:Red Hill F	eeder Date:	March 2013 Inspec	cted, by:				
Company:							
NCR required for Non Conformances YES/NO If Yes Process owner is NCR #							
On Site Documentation	Assessment	Comments	Action Required/Completed	By Who Due Date			
1. Has clearing work been done in accordance with the instructions in the WP?	Acceptable						
2. Has the Contractor done the clearing work in accordance with the instructions given to the Contractor?	Acceptable						
3. Is the Land Manager satisfied with work done	☐ Acceptable						

Reference documents:

- 1. Work Safety regulation 2009
- 2. Work Safety Act 2008.
- 3. ASNZS 1269 Occupational noise management Measurement and assessment of noise emission and exposure);
- 4. Code of practice First Aid





- 5. Guidance material for Traffic Risk Management Guide to Horticulture and Cleaning Industries
- 6. ActewAGL (electrical Rule Book) Blue Book
- 7. ActewAGL Standing Offer No.095/10
- 8. ActewAGL Procedure EN 4.2 P 12
- 9. ActewAGL Procedure EN 4.2 P 15

Inspector Comments

All works completed to ActewAGL standards 100% inspected





INSPECTION CHECKLIST FOLLOWING COMPLETION OF RURAL VEGETATION CLEARING WORK

Location: Wetlands	feeder	Date:	March	2013	Inspected,	by:			
Company:									
NCR required for Non Co	onformances	YES/NO	If Yes P	rocess owner	r is		NCR #		
On Site Documentation	Assessn	nent		Comments	S	Action Req	uired/Completed	By Who	Due Date
1. Has clearing work been done in accordance with the instructions in the WP?	Acceptable								
2. Has the Contractor done the clearing work in accordance with the instructions given to the Contractor?	Acceptable								
3. Is the Land Manager satisfied with work done	Acceptable								

Reference documents:

- 1. Work Safety regulation 2009
- 2. Work Safety Act 2008.
- 3. ASNZS 1269 Occupational noise management Measurement and assessment of noise emission and exposure);
- 4. Code of practice First Aid





- 5. Guidance material for Traffic Risk Management Guide to Horticulture and Cleaning Industries
- 6. ActewAGL (electrical Rule Book) Blue Book
- 7. ActewAGL Standing Offer No.095/10
- 8. ActewAGL Procedure EN 4.2 P 12
- 9. ActewAGL Procedure EN 4.2 P 15

Inspector Comments

All works completed to ActewAGL standards 100% inspected





INSPECTION CHECKLIST FOLLOWING COMPLETION OF RURAL VEGETATION CLEARING WORK

Location:		Date: 13/07/2012	Inspected, by:		
Company:				_	
·	onformances YES/NO	If Yes Process owner is			
On Site Documentation	Assessment	Comments	Action Required/Completed	By Who	Due Date
1. Has clearing work been	Needs Attention				
done in accordance with	Acceptable				
the instructions in the WP?					
2. Has the Contractor done	Needs Attention				
the clearing work in	☐ Acceptable				
accordance with the					
instructions given to the					
Contractor?					
3. Is the Land Manager	Acceptable				
satisfied with work done	Needs Attention				

Reference documents:

- 1. Work Safety regulation 2009
- 2. Work Safety Act 2008.
- 3. ASNZS 1269 Occupational noise management Measurement and assessment of noise emission and exposure);
- 4. Code of practice First Aid





- 5. Guidance material for Traffic Risk Management Guide to Horticulture and Cleaning Industries
- 6. ActewAGL (electrical Rule Book) Blue Book
- 7. ActewAGL Standing Offer No.095/10
- 8. ActewAGL Procedure EN 4.2 P 12
- 9. ActewAGL Procedure EN 4.2 P 15

Inspector Comments





INSPECTION CHECKLIST FOLLOWING COMPLETION OF RURAL VEGETATION CLEARING WORK

Location:		Date: 13/07/2012	Inspected, by:		
Company:					
NCR required for Non C	onformances YES/NO	If Yes Process owner is			
On Site Documentation 1. Has clearing work been done in accordance with the instructions in the WP?	Assessment Needs Attention Acceptable	Comments	Action Required/Completed	By Who	Due Date
2. Has the Contractor done the clearing work in accordance with the instructions given to the Contractor?	Needs Attention Acceptable				
3. Is the Land Manager satisfied with work done	Acceptable Needs Attention				

Reference documents:

- 1. Work Safety regulation 2009
- 2. Work Safety Act 2008.
- 3. ASNZS 1269 Occupational noise management Measurement and assessment of noise emission and exposure);
- 4. Code of practice First Aid





- 5. Guidance material for Traffic Risk Management Guide to Horticulture and Cleaning Industries
- 6. ActewAGL (electrical Rule Book) Blue Book
- 7. ActewAGL Standing Offer No.095/10
- 8. ActewAGL Procedure EN 4.2 P 12
- 9. ActewAGL Procedure EN 4.2 P 15

Inspector Comments





INSPECTION CHECKLIST FOLLOWING COMPLETION OF RURAL VEGETATION CLEARING WORK

Location: Tidebir	billa Feeder Date:	13/12/2012 I	nspected, by:					
Company:								
NCR required for Non Conformances YES/NO If Yes Process owner is NCR #								
On Site Documentation 1. Has clearing work been done in accordance with the instructions in the WP?	Assessment Needs Attention Acceptable	Comments	Action Requir	red/Completed	By Who	Due Date		
2. Has the Contractor done the clearing work in accordance with the instructions given to the Contractor?	Needs Attention Acceptable							
3. Is the Land Manager satisfied with work done	Acceptable Needs Attention							

Reference documents:

- 1. Work Safety regulation 2009
- 2. Work Safety Act 2008.
- 3. ASNZS 1269 Occupational noise management Measurement and assessment of noise emission and exposure);
- 4. Code of practice First Aid





- 5. Guidance material for Traffic Risk Management Guide to Horticulture and Cleaning Industries
- 6. ActewAGL (electrical Rule Book) Blue Book
- 7. ActewAGL Standing Offer No.095/10
- 8. ActewAGL Procedure EN 4.2 P 12
- 9. ActewAGL Procedure EN 4.2 P 15

Inspector Comments

50% inspected to ActewAGL standards





INSPECTION CHECKLIST FOLLOWING COMPLETION OF RURAL VEGETATION CLEARING WORK

Location: Cotto	er Feeders Da	ate: February 2013	Inspected, by:					
Company:								
NCR required for Non Conformances YES/NO If Yes Process owner is NCR #								
On Site Documentation 1. Has clearing work been done in accordance with the instructions in the WP?	Assessment Acceptable	Comments	Action Required/Completed	By Who	Due Date			
2. Has the Contractor done the clearing work in accordance with the instructions given to the Contractor?	Acceptable							
3. Is the Land Manager satisfied with work done	Acceptable							

Reference documents:

- 1. Work Safety regulation 2009
- 2. Work Safety Act 2008.
- 3. ASNZS 1269 Occupational noise management Measurement and assessment of noise emission and exposure);
- 4. Code of practice First Aid





- 5. Guidance material for Traffic Risk Management Guide to Horticulture and Cleaning Industries
- 6. ActewAGL (electrical Rule Book) Blue Book
- 7. ActewAGL Standing Offer No.095/10
- 8. ActewAGL Procedure EN 4.2 P 12
- 9. ActewAGL Procedure EN 4.2 P 15

Inspector Comments

All works completed to ActewAGL standards 50% inspected





INSPECTION CHECKLIST FOLLOWING COMPLETION OF RURAL VEGETATION CLEARING WORK

Location: Mathews	feeder	Date:	March	2013	Inspected	, by:			
Company:									
NCR required for Non Co	onformances	YES/NO	If Yes Pr	ocess owner	· is		NCR #		
On Site Documentation 1. Has clearing work been done in accordance with the instructions in the WP?	Assessm Acceptable			Comments	S	Action Req	uired/Completed	By Who	Due Date
2. Has the Contractor done the clearing work in accordance with the instructions given to the Contractor?	Acceptable								
3. Is the Land Manager satisfied with work done	Acceptable								

Reference documents:

- 1. Work Safety regulation 2009
- 2. Work Safety Act 2008.
- 3. ASNZS 1269 Occupational noise management Measurement and assessment of noise emission and exposure);
- 4. Code of practice First Aid





- 5. Guidance material for Traffic Risk Management Guide to Horticulture and Cleaning Industries
- 6. ActewAGL (electrical Rule Book) Blue Book
- 7. ActewAGL Standing Offer No.095/10
- 8. ActewAGL Procedure EN 4.2 P 12
- 9. ActewAGL Procedure EN 4.2 P 15

Inspector Comments

All works completed to ActewAGL standards 70% inspected





INSPECTION CHECKLIST FOLLOWING COMPLETION OF RURAL VEGETATION CLEARING WORK

Location: Rei	d Feeder	Date:	13/12/2012	Inspected, I	oy:			
Company:								
NCR required for Non (Conformances	YES/NC	If Yes Process o	wner is		NCR #		
On Site Documentation 1. Has clearing work been done in accordance with the instructions in the WP?	Assessr Acceptable		Comm	nents	Action Required/C	Completed	By Who	Due Date
2. Has the Contractor done the clearing work in accordance with the instructions given to the Contractor?	Acceptable							
3. Is the Land Manager satisfied with work done	☐ Acceptable							

Reference documents:

- 1. Work Safety regulation 2009
- 2. Work Safety Act 2008.
- 3. ASNZS 1269 Occupational noise management Measurement and assessment of noise emission and exposure);
- 4. Code of practice First Aid





- 5. Guidance material for Traffic Risk Management Guide to Horticulture and Cleaning Industries
- 6. ActewAGL (electrical Rule Book) Blue Book
- 7. ActewAGL Standing Offer No.095/10
- 8. ActewAGL Procedure EN 4.2 P 12
- 9. ActewAGL Procedure EN 4.2 P 15

Inspector Comments

All works completed to ActewAGL standards





INSPECTION CHECKLIST FOLLOWING COMPLETION OF RURAL VEGETATION CLEARING WORK

Location: Mt A	inslie/Campbell fe	eder Date:	February 2013	Inspected, by:					
Company:			-						
NCR required for Non Conformances YES/NO If Yes Process owner is NCR #									
On Site Documentation 1. Has clearing work been done in accordance with the instructions in the WP?	Assessment Acceptable	Comme	ents Ad	ction Required/Completed	By Who	Due Date			
2. Has the Contractor done the clearing work in accordance with the instructions given to the Contractor?	Acceptable								
3. Is the Land Manager satisfied with work done	☐ Acceptable								

Reference documents:

- 1. Work Safety regulation 2009
- 2. Work Safety Act 2008.
- 3. ASNZS 1269 Occupational noise management Measurement and assessment of noise emission and exposure);
- 4. Code of practice First Aid





- 5. Guidance material for Traffic Risk Management Guide to Horticulture and Cleaning Industries
- 6. ActewAGL (electrical Rule Book) Blue Book
- 7. ActewAGL Standing Offer No.095/10
- 8. ActewAGL Procedure EN 4.2 P 12
- 9. ActewAGL Procedure EN 4.2 P 15

Inspector Comments

All works completed to ActewAGL standards 50% inspected





INSPECTION CHECKLIST FOLLOWING COMPLETION OF RURAL VEGETATION CLEARING WORK

Location: Holm	nan feeder Da	te: February 2013	Inspected, by:		
Company:					
NCR required for Non C	onformances YES/NC) If Yes Process owner is _	NCR #		
On Site Documentation 1. Has clearing work been done in accordance with the instructions in the WP?	Assessment Acceptable	Comments	Action Required/Completed	By Who	Due Date
2. Has the Contractor done the clearing work in accordance with the instructions given to the Contractor?	Acceptable				
3. Is the Land Manager satisfied with work done	Acceptable Acceptable				

Reference documents:

- 1. Work Safety regulation 2009
- 2. Work Safety Act 2008.
- 3. ASNZS 1269 Occupational noise management Measurement and assessment of noise emission and exposure);
- 4. Code of practice First Aid





- 5. Guidance material for Traffic Risk Management Guide to Horticulture and Cleaning Industries
- 6. ActewAGL (electrical Rule Book) Blue Book
- 7. ActewAGL Standing Offer No.095/10
- 8. ActewAGL Procedure EN 4.2 P 12
- 9. ActewAGL Procedure EN 4.2 P 15

Inspector Comments

All works completed to ActewAGL standards 50% inspected





INSPECTION CHECKLIST FOLLOWING COMPLETION OF RURAL VEGETATION CLEARING WORK

Location: Mona	ash Feeder Da	te: February 2013	Inspected, by:						
Company:									
NCR required for Non Conformances YES/NO If Yes Process owner is NCR #									
On Site Documentation 1. Has clearing work been done in accordance with the instructions in the WP?	Assessment Acceptable	Comments	Action Required/Completed	By Who	Due Date				
2. Has the Contractor done the clearing work in accordance with the instructions given to the Contractor?	Acceptable								
3. Is the Land Manager satisfied with work done	Acceptable Acceptable								

Reference documents:

- 1. Work Safety regulation 2009
- 2. Work Safety Act 2008.
- 3. ASNZS 1269 Occupational noise management Measurement and assessment of noise emission and exposure);
- 4. Code of practice First Aid





- 5. Guidance material for Traffic Risk Management Guide to Horticulture and Cleaning Industries
- 6. ActewAGL (electrical Rule Book) Blue Book
- 7. ActewAGL Standing Offer No.095/10
- 8. ActewAGL Procedure EN 4.2 P 12
- 9. ActewAGL Procedure EN 4.2 P 15

Inspector Comments

All works completed to ActewAGL standards 100% inspected





INSPECTION CHECKLIST FOLLOWING COMPLETION OF RURAL VEGETATION CLEARING WORK

Location: Date:	January 25 2012	Inspected, by:			
Company:					
NCR required for Non Co	onformances YES/NO	If Yes Process owner is	NCR #		
On Site Documentation 1. Has clearing work been done in accordance with the instructions in the WP?	Assessment Needs Attention Acceptable	Comments	Action Required/Completed	By Who	Due Date
2. Has the Contractor done the clearing work in accordance with the instructions given to the Contractor?	Needs Attention Acceptable				
3. Is the Land Manager satisfied with work done	Acceptable Needs Attention				

Reference documents:

- 1. Work Safety regulation 2009
- 2. Work Safety Act 2008.
- 3. ASNZS 1269 Occupational noise management Measurement and assessment of noise emission and exposure);
- 4. Code of practice First Aid





- 5. Guidance material for Traffic Risk Management Guide to Horticulture and Cleaning Industries
- 6. ActewAGL (electrical Rule Book) Blue Book
- 7. ActewAGL Standing Offer No.095/10
- 8. ActewAGL Procedure EN 4.2 P 12
- 9. ActewAGL Procedure EN 4.2 P 15

Inspector Comments





INSPECTION CHECKLIST FOLLOWING COMPLETION OF RURAL VEGETATION CLEARING WORK

Location; 132 B	lack Mountain to I	/lacgregor	Date: 、	January 25 2012	Inspected, by:		
Company:							
NCR required for Non Co	onformances YES/NO	If Yes Process	s owner is		NCR #		
On Site Documentation	Assessment	Cor	mments	Action Requ	ired/Completed	By Who	Due Date
1. Has clearing work been done in accordance with the instructions in the WP?	Needs Attention Acceptable						
2. Has the Contractor done the clearing work in accordance with the instructions given to the Contractor?	Needs Attention Acceptable						
3. Is the Land Manager satisfied with work done	☐ Acceptable ☐ Needs Attention						

Reference documents:

- 1. Work Safety regulation 2009
- 2. Work Safety Act 2008.
- 3. ASNZS 1269 Occupational noise management Measurement and assessment of noise emission and exposure);
- 4. Code of practice First Aid





- 5. Guidance material for Traffic Risk Management Guide to Horticulture and Cleaning Industries
- 6. ActewAGL (electrical Rule Book) Blue Book
- 7. ActewAGL Standing Offer No.095/10
- 8. ActewAGL Procedure EN 4.2 P 12
- 9. ActewAGL Procedure EN 4.2 P 15

Inspector Comments





INSPECTION CHECKLIST FOLLOWING COMPLETION OF RURAL VEGETATION CLEARING WORK

Location; 132 B	lack Mountain to I	/lacgregor	Date: 、	January 25 2012	Inspected, by:		
Company:							
NCR required for Non Co	onformances YES/NO	If Yes Process	s owner is		NCR #		
On Site Documentation	Assessment	Cor	mments	Action Requ	ired/Completed	By Who	Due Date
1. Has clearing work been done in accordance with the instructions in the WP?	Needs Attention Acceptable						
2. Has the Contractor done the clearing work in accordance with the instructions given to the Contractor?	Needs Attention Acceptable						
3. Is the Land Manager satisfied with work done	☐ Acceptable ☐ Needs Attention						

Reference documents:

- 1. Work Safety regulation 2009
- 2. Work Safety Act 2008.
- 3. ASNZS 1269 Occupational noise management Measurement and assessment of noise emission and exposure);
- 4. Code of practice First Aid





- 5. Guidance material for Traffic Risk Management Guide to Horticulture and Cleaning Industries
- 6. ActewAGL (electrical Rule Book) Blue Book
- 7. ActewAGL Standing Offer No.095/10
- 8. ActewAGL Procedure EN 4.2 P 12
- 9. ActewAGL Procedure EN 4.2 P 15

Inspector Comments